Weighing CWB7 Service Manual

Power Source

100~240V 50/60hz AC INTPUT 12V/1A DC OUTPUT 12W 6V/4AH Lead-acid rechargeable battery included

Power Consumption

Approx. 12mA Approx. 36mA with backlight Approx. 48mA with backlight and RS232 interface

Battery hours per charge

Approx. 320 hours (backlight off)

OPTION

RS232 Interface

LOADCELL connection (for indicator)

PIN1 : E + PIN2 : SEN+ PIN3 : E- PIN4 : SEN-PIN5 : S+ PIN6 : GND PIN7 : S -

How to display version number?

Turn on the scale and press and hold the $ZERO / \blacktriangleleft$ key until the countdown sequence has completed. The LCD display will show 1001 . The shown number is the software version of the scale. Release the $ZERO / \blacktriangleleft$ key and the scale will start the functions setup

Display





- ZERO / ◀ key:
- ZERO : To reset the weight to 0, but the displayed weight value has to be less than ± 2% of maximum capacity.

 \blacktriangleleft : To move one space to the left or downward in setup mode.

To the left

 $00000\underline{0} \rightarrow 0000\underline{0}0 \rightarrow 000\underline{0}00 \rightarrow 00\underline{0}000 \rightarrow 0\underline{0}0000 \rightarrow \underline{0}00000$

Downward

 $\text{LF } 8 \rightarrow \text{LF } 7 \rightarrow \text{LF } 6 \rightarrow \cdots \rightarrow \text{LF } 1$

 $\text{UF-11} \rightarrow \text{UF-10} \rightarrow \text{UF-9} \rightarrow \cdots \rightarrow \text{UF-1}$

 $ECF-3 \rightarrow ECF-2 \rightarrow ECF-1$

TARE / ► key: TARE : To subtract the container weight. Maximum tare = full capacity ▶ : To move one space to the right or upward in setup mode. To the right Upward $LF \ 1 \rightarrow LF \ 2 \rightarrow LF \ 3 \rightarrow \cdots \rightarrow LF \ 8$ $UF-1 \rightarrow UF-2 \rightarrow UF-3 \rightarrow \cdots \rightarrow UF-11$ $ECF-1 \rightarrow ECF-2 \rightarrow ECF-3$ N/G/ ▲ key: Net/Gross : To see gross and net weight when the scale is on tare status. All other keys will be disabled when gross weight is activated. ▲ : To increase values upward in setup mode. 例如 : 232 0 → 232 1 → 232 2 → 232 3 → …… → 232 6 PRINT / ↓ key: PRINT : Manually transmitting data through RS232 to computer or printer at normal weighing mode (RS232 setup must be set at keyboard transmission 232 3 or 232 6) ↓ : Works as enter key in setup mode i interset in State Err H Initial zero too high (over FULL SCALE + 10%), For approval models Err L Initial zero too low (under FULL SCALE - 10%), For approval models Unstable internal count Err N -0L-Overload, when the weight is heavier than the full capacity + 9d of the scale

Functions Setup

Approval Calibrations and Functions Setup (Lock section) L F 1 ~ 8 Standard Functions Setup UF - 1 ~ 11 Standard Calibrations ECF - 1 ~ 3

Standard Calibrations:					
Press the ZERO / < key and the PRINT / < key in weighing mode to start					
Standard Calibrations					
ECF-1 Weight Calibration (Zero and Span)					
ECF-2 Zero Calibration					
ECF-3 Span Calibration					
st When the scale is programmed for Approval (LF 6), standard					
calibration will be locked					
PRINT / + N/G/ A : A					
ZERO /					
TARE / ► : ►					
ECF-1 Press the ← key to start or press the ESC key to exit					
menu and back to weighing mode					
ECF-2 Press the + key to start or press the ESC key to exit					
menu and back to weighing mode					
\checkmark \checkmark \checkmark \blacktriangleright					
ECF-3 Press the 4 key to start or press the ESC key to exit					
menu and back to weighing mode					

ECF-1 Weight Cal	libration :
ECF-1	Press the 4 key to start Weight Calibration (Press
	the ESC key to exit back to weighing mode)
\checkmark	
له	
CALZ	Press the 4 key to calibrate zero point (Press the
	ESC key to terminate calibration back to menu ECF-1)
\checkmark	
ل	
<u>1</u> 50.00kg	Use ◀,▶,▲ and then ◀ key to enter the weight to be
	calibrated
CWB7	4

	(Press the ESC key to terminate calibration back to
جا	menu ECF-1)
150.00kg	Place the required weight mass onto the scale as
	indicated on display and press the ↓ key to calibrate
	the scale
	(Press the ESC key to terminate calibration back to
4	menu ECF-1)
150.00kg	Calibration procedure completed and the scale will
	return back to weighing mode automatically
	-
ECF-2 Zero Calil	pration :
ECF - 2	Press the 🛃 key to start Zero Calibration (Press the
	ESC key to exit back to weighing mode)
\downarrow	
4 A	
CALZ	Press the 🖌 key to calibrate zero point (Press the
	ESC key to terminate calibration back to menu ECF-2)
\downarrow	
4	
().()()kg	Zero Calibration procedure completed and the scale
	will return back to weighing mode automatically
ECE 3 SDAN Cali	hration ·
ECE 2	
ECF-3	Press the \checkmark key to start Span Calibration (Press the
	ESC key to exit back to weighing mode)
. ↓	
↔ 150 00.	
130.00kg	Use ◀,▶,▲ and then ◀ key to enter the weight to be
<u> </u>	calibrated
↓	(Press the ESC key to terminate calibration back to
4 150 00	menu ECF-3)
15U.UUkg	Place the required weight mass onto the scale as
	indicated on display and press the 🖌 key to calibrate
	the scale



- UF-6 RS232 Output
- ↔UF-7 ADC Update Rate
- ♣UF-8 Display Condition at Zero
 - UF-9 Gravitational (G value) Pre-Calibration
 - UF-10 Filter set
- UF-11 Stable range

►

►

★ ♣ marks function locked when LF 6 is set as "Approval Version"

PRINT / 🗸	:	لۍ	N/G/ ▲	:	▲	
ZERO / ┥	:	•	UNITS/ ESC	:	ESC	
TARE / 🕨	:	►				



UF-2

UF-3

Press the ← key to start or press the ESC key to exit menu and back to weighing mode

Press the *+* key to start or press the ESC key to exit menu and back to weighing mode

Press the ↓ key to start or press the ESC key to exit menu and back to weighing mode

Press the 🖌 key to start or press the ESC key to exit





UF-2 Check Weigh	ing :					
0000.0L Set]	LO (low) weight					
0000.0H Set HI (high) weight						
0 000 Program I/O conditions						
X LO set as 0 w	ill clear all check weigh values					
💥 Check weighing	g conditions can be set independently for each of the					
weighing unit	s and counting mode					
ℜ All settings	will be saved until manually cleared					
℁ Last entry wi	11 be displayed before setup					
* This function	is locked when UF-5 is set as "HOLD 1"					
UF-2	Press the 🖌 key to start or press the ESC key to exit					
	menu and back to weighing mode					
له						
0000.0L	Use ◀,▶,▲ and then ◀ key to set LO weight value					
\longrightarrow	(Press the ESC key to exit the setup and back to menu					
له	UF-2)					
0000.0H	Use ◀,▶,▲ and then ◀ key to set HI weight value					
\downarrow	(Press the ESC key to exit the setup and back to menu					
له	UF-2)					
0 000	Use ◀,▶,▲ and then ◀ key to set I/O SET value					
\downarrow	(Press the ESC key to exit the setup and back to menu					
ج ا	UF-2)					
UF-2	Use \checkmark and then \checkmark key to continue with other setups					
	or press the ESC key to exit menu and back to weighing					
	mode					
	- CC .					
UF-3 Auto Power-	011 :					
AoFF 00 Auto pow	er-off disable					
AoFF 01 The scale	e turns off automatically in 1 minute when the scale					
S						
not in operation	and weight at O					
Auto power-off t	imer up to 99 minutes (AoFF01~AoFF 99)					

Auto power-off timer up to 99 ※ Factory default: AoFF 10



UF-5 Hold :				
HOLD 0	Hold function off			
HOLD 1	Animal (motion) Hold function			
PCt XXX	To set the range from 001 ~ 100 of the animal hold			
	(for HOLD 1 only)			



Weighing UF-5) UF-5 Use \checkmark and then \checkmark key to continue with other setups or press the ESC key to exit menu and back to weighing mode UF-6 RS232 : RS232 disable 232 0 232 1 Stable output - Format 1 232 2 Stream output - Format 1 232 3 Manual output - Format 1 232 4 Stable output - Format 2 232 5 Stream output - Format 2 232 6 Manual output - Format 2 RS232 Baud rate b 1200 Baud rate 1200 Baud rate 2400 b 2400 b 4800 Baud rate 4800 b 9600 Baud rate 9600 b19200 Baud rate 19200 b38400 Baud rate 38400 Communication Protocol UART signal of EIA-RS232 C Format : 1. Serial output: 1200 / 2400 / 4800 / 9600 / 19200 / 38400 BPS 2. Data bits : 8 BITS 3. Parity bits : None 4. Stop bits : 1 BIT Start bit Data bits Stop bits Format 1 (232 1 ~ 3) :

HEAD2 (2 BYTES)

HEAD1 (2 BYTES)

CT Ct-11	
51 - Stable	INI - INET Weight
US - Unstable	GS - Gross Weight
Fixed 18 BYTES ASCII (kg	g t lb)
HEAD1, HEAD2, DATA	UNIT CR LF
Fixed 21 BYTES ASCII (t1	.T lboz)
1 2 1 1 2 1 1 2 3 4	5 6 7 8 9 1 2 3 4 1 2
HEAD1, HEAD2, DAT	TA UNIT CR LF
Fixed 19 BYTES ASCII (pc	s)
1 2 1 1 2 1 1 2 3	4 5 6 7 8 1 2 3 1 2
HEAD1 . HEAD2 . DA	ATA INIT CR IF
Output examples :	
1. Example +0.876 kg Stab	le net weight :
S T , N T , + 0 0 0	. 8 7 6 k g OD OA
2. Example -1.568 lb unst	able gross weight :
U S , G S , - 0 0 1	. 5 6 8 1 b OD OA
3 Example -20. 5.40 lb oz	unstable gross weight :
S T , G S , - 1 0 .	0 5 . 4 0 1 b o z 0D 0A
4 Example +1000 pcs stabl	e net weight :
S T , N T , + 0 0 0	1 0 0 0 p c s 0D 0A
Format 2 $(232 \ 4 \sim 6)$:	
Fixed 12 BYTES ASCII (kg	g t lb)
1 2 3 4 5 6 7	8 1 2 1 2
DATA	UNIT CR LF
Fixed 15 BYTES ASCII (tl	.T lboz)
1 2 3 4 5 6 7	8 9 1 2 3 4 1 2
DATA	UNIT CR LF
Fixed 13 BYTES ASCII (pc	s)
1 2 3 4 5 6	7 8 1 2 3 1 2

DATA UNIT CR LF
Output examples :
1. Example +0.876 kg stable net weight :
+ 0 0 0 . 8 7 6 k g OD OA
2. Example -1.568 lb unstable gross weight :
- 0 0 1 . 5 6 8 1 b OD OA
3 Example -20. 5.40 lb oz unstable gross weight :
- 1 0 . 0 5 . 4 0 1 b o z OD OA
4 Example +1000 pcs stable net weight :
+ 0 0 0 1 0 0 p c s 0D 0A
≫ Factory default: 232 0
UF-6 Press the ← key to start or press the ESC key to exit
menu and back to weighing mode
<u>ل</u>
232 0 Use ▲ and then ↓ key to enter RS232 output format
(Press the ESC key to exit the setup and back to menu
UF-6)
\checkmark
<u>ل</u>
b 9600 Use A and then A key to select baud rate
(Press the ESC key to exit the setup and back to menu
UF-6)
\checkmark
<u>ل</u>
UF-6 Use ◀► and then ◄ key to continue with other setups
or press the ESC key to exit menu and back to weighing
mode
UF-7 ADC Update Rate :
SPEEd 1 Standard speed 15 hz
SPEEd 2 High speed 30 hz
SPEEd 3 Low speed 7.5 hz
* This function is locked when UF-5 is set as "HOLD 1"

* This function is locked when LF 6 is set as "Approval Version"						
× Factory default: SPEEd 1						
UF-7	Press the 🖌 key to start or press the ESC key to exit					
	menu and back to weighing mode					
\downarrow						
ل ه	1					
SPEEd 1	Use ▲ and then ↓ key to select ADC speed					
	(Press the ESC key to exit the setup and back to menu					
	UF-7)					
ل						
UF - 7	Use ◀.► and then ◀ key to continue with other setups					
	or press the ESC key to exit menu and back to weighing					
	mode					
	-					
UF-8 Zero Weigh	t Display Condition :					
ZP 0 Off						
ZP 1 One divi	ision not to display at zero					
ZP 2 Two dive	isions not to display at zero					
ZP 3 Three d	ivisions not to display at zero					
ZP 4 Four div	visions not to display at zero					
ZP 5 Five div	visions not to display at zero					
* This function	n is locked when UF-5 is set as "HOLD 1"					
* This function	n is locked when LF 6 is set as "Approval Version"					
💥 Factory defau	alt: ZP 0					
UF-8	Press the 🖌 key to start or press the ESC key to exit					
	menu and back to weighing mode					
	-					
له						
ZP 0	Use ▲ and then ✔ key to select how many divisions					
	not to display at zero					
	(Press the ESC key to exit the setup and back to menu					
	UF-8)					
· · · · · · · · · · · · · · · · · · ·						

ℯ UF-8

Use \triangleleft and then \triangleleft key to continue with other setups or press the ESC key to exit menu and back to weighing mode

UF-9 Standard Gravitational (G value) Pre-Calibration:

Approval Model: When the CAL switch is at OFF, 10 gravitational values can be entered and can be also recalled for reference. After 10 gravitational values have been filled, the scale will only allow recalling previous 10 values (-00- \sim -09-) for reference and adding new value will not be allowed. Internal Gravitational Calibration or LF1 Internal Weight Calibration has to be done to erase previously entered values.

Non-approval Model: Even the scale allows to do the Standard Calibration, Gravitational Calibration can help to provide accurate scale when end users received it without all the trouble to recalibrate the scale. Pre-calibration is allowed when the scale is setup as non-approval model or the CAL switch is at ADJ position. Gravitational value will be saved at -00- and will be replaced each time a new value has been entered.

X Sender G value: Set it before Weight Calibration

X Recipient G value: Set it after Weight Calibration

* The G value will be denied when the value is greater than 9.83217

(Polar G value) or less than 9.78031 (Equator G value)

* Factory Default: 9.79423



►

menu and back to weighing mode

Use \checkmark keys to see previous entered values. The

display will stay at 00 if no value has been entered



Select 1-4, Filter from low to high						
UF-10) Press the 🖌 key to start or press the ESC key to exi					
	menu and back to weighing mode					
\checkmark						
ل ہ						
FiLt 2	Use ▲ and then ↓ key to select filter modes					
	(Press the ESC key to exit the setup and back to menu					
	UF-10)					
\checkmark						
ل						
UF-10	Use ◀ ▶ and then ◀ key to continue with other setups					
	or press the ESC key to exit menu and back to weighing					
	mode					

UF-11 Stable range :					
1 :Low 2 :Medium 3 :High					
UF-11	Press the 4 key to start or press the ESC key to exit				
	menu and back to weighing mode				
\checkmark					
4					
StA 2	Use \blacktriangle and then \bigstar key to select stable modes				
	(Press the ESC key to exit the setup and back to menu				
	UF-11)				
\checkmark					
4					
UF-11	Use ◀► and then ◀ key to continue with other setups				
	or press the ESC key to exit menu and back to weighing				
	mode				
Approval Calibra	ations and Functions Setup (Lock section):				
Turn on the scal	e and press and hold the ZERO / < key until the countdown				
sequence becomes	1001, then release the ZERO / < key and the scale will				
show LF 1					
LF 1 Weight Cal	ibration				
LF 2 Spec Calibration					
LF 3 Linearity Calibration					
LF 4 ADC Update	e Speed				

- LF 5 Zero Weight Display Condition
- LF 6 Approval Conformity
- LF 7 Gravitational (G value) Pre-Calibration
- LF 8 Zero Weight Display Condition

* Password is required to use Lock Section when LF 6 is set as "none" and CAL switch is OFF

PRINT / 🗸	:	لہ	N/G/ ▲	:	•
ZERO / 🖣	:	٩	UNITS/ ESC	:	ESC
TARE / 🕨	:	►			



LF 1 Weight Calibration :

Calibration can be done with any weight, but the weight should not be less than 1/100 of the max. capacity and not to exceed the max.



B : American Sys	tem 0 : None 1 : 1b 2 : 1b oz
C : Other Units	0 : None 1 : TW Kg 2 : HK Kg 3 : VISS
D : PCS	0 : Off
	1 : On
E : Duo range	0 : Off
	1 : MULTI INTERVAL
	2 : MULTIRANGE
F : Calibration Unit 1 : Metric units as calibration unit	
	2 : American units as calibration unit
💥 lb oz unit ca	nnot be selected as calibration unit
ℜ The scale will	l not allow to continue to the next setup step if an
error has occ	urred during the programming
Third step	
<u>0</u> 0000kg	Use \blacktriangleleft and then \checkmark key to enter the max. capacity
	→ Showing the calibration unit
$ \begin{array}{c ccccc} Forth step \\ \hline d & 0.0 \\ \hline d & 0.000 \\ \hline d & 0.0000 \\ \hline 0.00000 \\ \hline \end{array} $	se ◀.► keys to move the position of the decimal point
$ \begin{array}{c c} Fifth step\\ \hline div & 01\\ \hline div & 02\\ \hline div & 05\\ \hline div & 10\\ \hline div & 20\\ \hline div & 50\\ \end{array} $	Press the ▲ key to select division
ℜ After enterin	g LF 2, the scale will display the last saved setup.
All steps hav	e to be completed to save the changes, otherwise the
scale will ke	ep the last setup
* Proceed with	Weight Calibration after LF2 Spec Calibration
LF 2	Press the 4 key to start and will display the
	internal value or press the ESC key to exit menu and
	Los and the proof the Los Rey to exit mond and



Press the ◀ key to return back to the previous calibration point		
Press the 🗸 key to save the calibration		
Press the ESC key to terminate calibration back to menu LF 3		
Suggest that the correction value is greater than max. capacity to		
ensure the measuring range is within linearity range		
Suggest the linearity calibration should be in three points 0 \sim 1/3 \sim		
2/3 · 1		
* Proceed with Weight Calibration after Linearity Calibration		
LF 3	Press the 🖌 key to start or press the ESC key to exit	
	menu and the scale will restart automatically	
↓		
W O	Press the ► key to calibrate zero (Press the ESC key	
	to terminate calibration back to menu LF 3)	
W 1	Place 1/3 weight mass of full capacity onto the scale	
	and press the ► key to calibrate 1/3 of the capacity	
	(Press the ESC key to terminate calibration back to	
	menu LF 3)	
W 2	Place 2/3 weight mass of full capacity onto the scale	
	and press the ► key to calibrate 2/3 of the capacity	
▲ ↑ ↓ ►	(Press the ESC key to terminate calibration back to	
·	menu LF 3)	
W 3	Place weight mass of full capacity onto the scale and	
	press the ▶ key to calibrate full capacity放	
▲ ↑ ↓ ►	(Press the ESC key to terminate calibration back to	
•	menu LF 3)	
W 4	Press the 4 key to complete linearity calibration	
\checkmark	(Press the ESC key to terminate calibration back to	
ل	menu LF 3)	
LF 3	Use ◀▶ and then ◀ key to continue with other setups	
	or press the ESC key to exit menu and the scale will	
	restart automatically	

LF 4 ADC Update Rate :		
SPEEd 1 Standard speed 15 hz		
SPEEd 2 High speed 30 hz		
SPEEd 3 Low speed 7.5 hz		
* This function is locked when UF-5 is set as "HOLD 1"		
💥 Factory default: SPEEd 1		
LF 4 Press the 4 key to start or press the ESC key to exit		
menu and back to weighing mode		
ل▶		
SPEEd 1 Use ▲ and then ↓ key to select ADC speed		
(Press the ESC key to exit the setup and back to menu		
LF 4)		
\checkmark		
<u>4</u>		
LF 4 Use ◀► and then ◀ key to continue with other setups		
or press the ESC key to exit menu and the scale will		
restart automatically		
LF 5 Zero Weight Display Condition :		
7P 0 0ff		
ZP 0 011 ZP 1 One division not to display at zero		
ZP 2 Two divisions not to display at zero		
ZP 3 Three divisions not to display at zero		
ZP 4 Four divisions not to display at zero		
ZP 5 Five divisions not to display at zero		
* This function is locked when UE-5 is set as "HOLD 1"		
* Factory default: ZP 0		
$\overline{\text{LF 5}}$ Press the 4 key to start or press the FSC key to exit		
menu and the scale will restart automatically		

₄ ZP \downarrow

0

Use ▲ and then ↓ key to select how many divisions not to display at zero



oiML EC approval; Initial Zero FULL SCALE ±10%, Manual Zero FULL SCALE ±2%, No standard calibration allowed

✤ Factory default: nonE

Press the 4 key to start or press the ESC key to exit menu and the scale will restart automatically





Use ▲ and then ↓ key to select approval or non-approval (Press the ESC key to exit the setup and back to menu



Use **▲** and then **↓** key to continue with other setups or press the ESC key to exit menu and the scale will restart automatically

LF 7 Internal Gravitational (G value) Pre-Calibration:

X Sender G value: Set it before Weight Calibration

LF 6)

- * Recipient G value: Set it after Weight Calibration
- * The G value will be denied when the value is greater than 9.83217 (Polar G value) or less than 9.78031 (Equator G value)
- ★ Factory Default: 9.79423

